







6 Wiring diagram

- 1) DIL-1C
- 2) DIL-2A
- 2) DIL-2C

7 Precautions for use

- Avoid installing relays where rain falls, or where there is a strong magnetic field, or near objects with he
- Excessive mechanical shock may cause relay failure.
- For wave soldering, max temperature 260, duration not exceeding 5s.

